

Order No.: DD+DIS217.02E



1 piece VE2WD MA1

**ADC Solo**  
Type 5155 / 100

**Centricity CR SP1001**  
Type 5155 / 200

| Rating             |             |                 | When?       |                 |                |
|--------------------|-------------|-----------------|-------------|-----------------|----------------|
| safety<br>relevant | reliability | new<br>function | immediately | next<br>service | as<br>required |
|                    | X           |                 |             | X               |                |

Please file this document in section 13 of your technical documentation

## Modification kit “C-clips Protection and Discharge Plate” applied to ADC Solo

## 1 Modification kit “C-clips protection and Discharge plate”

Order number: CM+9.5146.9040.0

### 1.1 Scope of Delivery

4 x C-clip protection plates

4 x Screws

1 x Discharge plate

1 x Installation Instructions DD+DIS109.02E



For ADC Solo only two of the four C-clips protection plates are needed. Discharge plate is not applicable for ADC Solo. It only has to be installed in ADC Compact.

### 1.2 Modification “C-clips protection”



This is a must-modification! C-clips protection plates avoid imprudent removal of scan rollers.

Incorrect reinsertion of scan rollers after cleaning causes broken c-clips and therefore a replacement of the complete slow scan unit is necessary. To avoid removal of scan rollers modification “C-clips Protection Plate” is introduced.



Protection plate has to be installed with the crank towards the scan roller. Install c-clips protection plates only on the upper rollers.



Do not remove lower rollers for cleaning purposes! This can be done by turning the clutch.